

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

RECEIVED

JAN 14 1994

DIVISION OF
OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 6-93 To (mo./yr.) 11-93
 2. DOGM File Number (Mine No): S/003/016
 3. Mine Name: CONGLOMERATE (DOVE CREEK QUARRIES)
 4. Mineral(s) Mined (or permitted to mine): QUARTZITE THIN FLAGSTONE
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
W 1/2 14, NW 1/4, Section 14, Township 13 N., Range 16 W.
1/4, 1/4, Section , Township , Range
1/4, 1/4, Section , Township , Range
 7. Name of Operator or Company: UTAH BUILDING STONE SUPPLY
 8. Permanent Street Address: 842 WEST 400 NORTH
City, State, Zip: WEST BOUNTIFUL, UTAH 84087
Phone: 801-295-0601
 9. Company Representative (or designated operator):
Name: PRESTON BOWN
Title: PARTNER
Business Address: GENERAL DELIVERY
City, State, Zip: PARK VALLEY, UTAH
Phone: 801-295-0601 801-871-4160
- ☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 250 TONS

3. How much **additional acreage** was disturbed during the past year? 0
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

MATERIAL REMOVED FROM EXPOSED LEDGE.

5. How much acreage was **reclaimed** during the past year? NONE

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

THE LEDGE THAT IS EXPOSED RETREATS AS WE TAKE STONE. LARGE QUANTITIES ARE REMOVED BEFORE SURFACE DISTURBANCE IS NECESSARY, BUT PRODUCTION IS ONGOING.

7. What is the **total disturbed acreage** at years end? THREE (3) ACRES

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

WE PLAN TO EXPAND OUR WORK PAD SOME THIRTY FEET BY 150 FEET THIS YEAR. HOWEVER IT WILL BE A MATTER OF LEVELING OUT PAST QUARRY FACE (AS THE FACE OR WALL IS TAKEN, THE "PAD" SIZE INCREASES AND LEVELING IS DONE.)

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

PRESTON BOWN

Title of Operator:

PARTNER

Signature of Operator:

Preston Bown

Date:

1-12-94